

Date: Thursday, 30/11/2006 11:48:54 AM  
 User: Linda Lacelle

## Process Sheet

<b>Customer</b> : CC-DAR01 Dart Aerospace Ltd.	<b>Drawing Name</b> : D206-628-031/32/33/34
<b>Job Number</b> : 29728	
<b>Estimate Number</b> : 10804	
<b>P.O. Number</b> : <i>N/A</i>	<b>Part Number</b> : Z_CUSTOM
<b>This Issue</b> : 30/11/2006 <b>S.O. No.</b> : <i>N/A</i>	<b>Drawing Number</b> : DESTROY-CAR 188
<b>Prsht Rev.</b> : NC	<b>Project Number</b> : <i>N/A</i>
<b>First Issue</b> : <i>N/A</i> <b>Type</b> : LARGE FAB ASSY	<b>Drawing Revision</b> : <i>N/A</i>
<b>Previous Run</b> : 00015	<b>Material</b> : <i>N/A</i>
<b>Written By</b> : <i>[Signature]</i>	<b>Due Date</b> : 07/12/2006 <b>Qty:</b> 1 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> : <i>[Signature]</i>	
<b>Comment</b> :	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	QC5	INSPECT WORK TO CURRENT STEP



Comment: REMOVE FROM STOCK

PER CAR 188

D206-628-031 *B8884 Qty 3*~~D206-628-032 *B8885 Qty 2*~~~~*B8284 Qty 1*~~~~D206-628-033 *B13986 Qty 2*~~~~*B11254 Qty 1*~~~~D206-628-034 *B13987 Qty 2*~~~~*B11255 Qty 1*~~*206/11/30*

2.0	D206628031	Heli-Access-Step LH
-----	------------	---------------------



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)

Heli-Access-Step LH

3.0	D206628032	Heli-Access-Step RH
-----	------------	---------------------



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)

Heli-Access-Step RH

4.0	D206628033	Heli-Access-Step LH
-----	------------	---------------------



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)

Heli-Access-Step LH

Date: Thursday, 30/11/2006 11:48:54 AM  
User: Linda Lacelle

## Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D206-628-031/32/33/34

Job Number: 29728

Part Number: Z\_CUSTOM

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

D206628034

Heli-Access-Step RH



Comment: Qty.: 3.0000 Each(s)/Unit Total: 3.0000 Each(s)  
Heli-Access-Step RH

6.0

MISC

MISCELLANEOUS



Comment: MISCELLANEOUS  
REMOVE STEPS & PAPERWORK FROM BOX  
AND DESTROY

SAD

06:11:30



7.0

PACKAGING 1

PACKAGING RESOURCE #1



U061207

Comment: PACKAGING RESOURCE #1  
REMOVE ALL HARDWARE FROM BOXES  
AND RESTOCK  
RECORD ALL QTY'S / P/N'S & B/N'S BELOW:

P410/4

23

02731-1 B 9112 33x 02731-3 B 9442 16x 9.0 M S21042-4 M 6844 24  
B 8302 2x 9113 29x  
B 9441 13x 7.39 B 14652 3x M S21042-4 M 5289 70x

02844-1 B 11188 8x 02844-3 B 11189 2x 40 02844-4 B 14086 4x 40

AN3-4A B 8912 12x AN4-12A M 10107 13x M S21042-4 M 9963 48  
B 3455 1x M 9599 19x M 9910 20x 23 M 607120x 36x  
B 4785 5x

AN4-11A M 5343 40x 23 M 7086 8x AN9605010 M 6140 18x 03  
M 8942 24x AN9605016 M 9910 60x 03  
M 1000560x M 6088 24

Date: Thursday, 30/11/2006 11:48:55 AM  
User: Linda Lacelle

## Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D206-628-031/32/33/34

Job Number: 29728

Part Number: Z\_CUSTOM

Job Number:



Seq. #:

Machine Or Operation:

Description :

8.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

*2806/12/07*

Job Completion



*U 26-12-06*